



---

# Automation in Transportation Accidents

Deborah Bruce

National Transportation Safety  
Board


Washington, DC



# Automation Accidents

---

**Control  
System  
Design**



## **AUTOMATION ACCIDENTS**

occur when there is a  
disconnect between the  
control system and  
operator


## **Person**

- Monitoring
- Task overload
- Expectancy
- Inattention
- Complacency
- etc...



# The Role of Automation

- Transportation databases focus on fatalities
- Automation-related mistakes difficult to analyze
- Varied and inconsistent taxonomies





# Accident Examples

---

- Washington Metro Train Collision
  - Shady Grove MD on Jan 6, 1996
- Grounding of the Royal Majesty
  - Near Nantucket on June 10, 1995
- Pipeline release of hazardous liquid
  - Near Gramercy LA on May 23, 1996
- A300 Inflight Upset
  - Near West Palm Beach FL on May 12, 1997



# Metro train





# Pre-Accident Events

---

- Severe snow storm track conditions worsening.
- All Metrorail trains were functioning in Automatic train operation as opposed to Manual operations.
- Computerized system at Metro's Operations Control Center controls train acceleration, speed, and braking.
- Train operator responsible primarily for monitoring train functions and ensuring safe operations.





# Metrorail Operations Control Center

---

- Controllers monitor and direct operations throughout the system.
- Controllers set parameters for trains by assigning the train's "performance levels" (train's acceleration and top speed).
- Under new Metro policy, controllers were not permitted to authorize train operators to change from automatic to manual mode except in emergencies.



# Metro Operating Practices

---

- High number of wheel flats on Metro train . . . because of braking slides in manual mode.
- The November 17, 1995, notice instructing controllers *not* to permit train operators to change to manual mode (except in emergencies).
- The Jan. 6, 1996 storm was the first serious snow storm after change - - first real test of the new policy.





# Accident Sequence

---

- Controllers instructed the train to continue Automatic mode, set speed at lower performance level (59 mph).
- Train overruns Twinbrook Station (told by controllers not to service station go to next in Automatic mode).
- The train then overran Rockville Station by one car. Results in *performance level* loss because the train was not within platform limits.
- Thus, the train departed to Shady Grove Station at 75 mph (rather than 59 mph). Train overran station by 470 ft, struck and telescoped 21 feet into standing train.



# NTSB Findings

---

- Safety Board found over reliance on system automation to ensure safe train operations.
- Controllers had responsibility for day-to-day train operations, but lacked authority.
- For the 20 year history of Metrorail, controllers routinely gave permission for train operators to change to manual operation during periods of inclement weather.
- Controllers felt that train operator could do a better job of controlling the trains manually in slippery track conditions.



# NTSB Conclusions

---

- Metro management practices were inconsistent with complex automated rail system.
- Decisions for highly technical automated systems usually affect other activities (and sometimes produce unanticipated hazards).
- Metrorail management failed to fully understand the design features and limitations of the automatic train control system--
- Which led to unjustified management confidence that the system could ensure safe train operation under all operating conditions.




# Royal Majesty

---





# Navigational Track







# Integrated Control Bridge

---





# Chartroom







# GPS Display





# Pipeline Control System

---





# SCADA System


---







# Process Control Screen








| SILENCE               | -Rocky Mountain | -Gulf Coast Products   | -Gulf Coast Crude | -Midwest Products | -Midwest Crude | -Kentucky | -Ohio             |
|-----------------------|-----------------|--|-------------------|-------------------|----------------|-----------|-------------------|
| General Alarm Summary |                 | Tank 5 - Chatham 8" Crude  |                   |                   |                |           | 01/29/00 10:29:19 |
|                       |                 | Page: 1  |                   |                   |                |           | Goto Top          |
| Date/Time             | Group           | Alarm Description  |                   |                   |                |           |                   |
| 01/29/00 10:00:31     | TNK5_CHAT 8     | Tank 5 - Chatham: PLM - ALARM - 2hr (-436.6), 4hr (-429.6).                  |                   |                   |                |           |                   |
| 01/29/00 09:00:31     | CHAT_MAPL       | Chatham MAPL Station: PLM - ALARM - 2hr (391.3), 4hr (392.4), 24hr (1914.6). |                   |                   |                |           |                   |
| 01/29/00 03:00:30     | EAST_CAMERON_8  | East Cameron - Vermilion: PLM - ALARM - 4hr (NORMAL), 24hr (1548.0).         |                   |                   |                |           |                   |
| 01/28/00 17:00:31     | CSPR_SALS 20    | Guernsey Station: PLM - ALARM - 4hr (NORMAL), 24hr (7134.8).                 |                   |                   |                |           |                   |
| 01/26/00 00:43:08     | CHAT_CSPR 16    | Chatham_PLT: Lockout Unit 5: Change to state ALARM.                          |                   |                   |                |           |                   |

| CPM Detail   |         |         | Martinsville - Lima |         |         |         |
|--------------|---------|---------|---------------------|---------|---------|---------|
|              | ST 1    | ST 2    | ST 3                | LT 1    | LT 2    | LT 3    |
| Period       | 5 min   | 15 min  | 60 min              | 2 Hr    | 4 Hr    | 24 Hr   |
| Deviation    | 2       | 11      | 65                  | -3      | -9      | 309     |
| Percent      | 0.2     | 0.5     | 0.7                 | -0.0    | -0.0    | 0.2     |
| Meter In     | 759     | 2325    | 9236                | 16208   | 31594   | 183929  |
| Meter Out    | 805     | 2297    | 8691                | 16278   | 31653   | 183939  |
| Delta Meter  | 46      | -28     | -545                | 70      | 59      | 10      |
| Linepack     | -44     | 39      | 610                 | -73     | -68     | 299     |
| Alarm Type   | Volume  | Volume  | Volume              | Percent | Percent | Percent |
|              | Vol Pct | Vol Pct | Vol Pct             | Vol Pct | Vol Pct | Vol Pct |
| Over Limits  | 300     | 450     | 750                 | 750     | 750     | 1500    |
| (%) Flow     | 45.0    | 18.0    | 7.5                 | 4.5     | 2.0     | 0.6     |
| (%) Volume   | 342     | 418     | 693                 | 729     | 632     | 1104    |
| Short Limits | -200    | -300    | -500                | -500    | -750    | -1500   |
| (%) Flow     | -30.0   | -12.0   | -5.0                | -3.0    | -2.0    | -0.6    |
| (%) Volume   | -228    | -279    | -462                | -486    | -632    | -1104   |

Balance Signature

|              |  |                       |  |                       |  |  |  |                  |      |                  |  |           |  |
|--------------|--|-----------------------|--|-----------------------|--|--|--|------------------|------|------------------|--|-----------|--|
| Flow Rates   |  | MRTV - LEBN Pressures |  | LEBN - LIMA Pressures |  | Yellow = Now - 20 minutes<br>Green = 20 - 40 minutes<br>Blue = 40 - 60 minutes |  | Unpack           | Data |                  |  |           |  |
| NOTES        |  | HELP                  |  | Event History         |  |  |  | Leak             | Pack |                  |  |           |  |
| Short Term 1 |  | Short Term 2          |  | Short Term 3          |  | Long Term 1  |  | Long Term 2      |      | Long Term 3      |  |           |  |
| ACTIVATE     |  | SUSPEND               |  | Meter Summary         |  | Linepack Summary   |  | Short Term Array |      | Reset Short Term |  | Reset ALL |  |
| DISMISS      |  |                       |  |                       |  | Long Term Array  |  | Reset Long Term  |      | Reset Alarm      |  |           |  |



Page Acknowledge



# A300-600 Inflight Upset

---





# Event Sequence


---

- Autothrottle set to hold 210 knots
- Engaged at start of descent from FL240
  - During descent - power reduced from idle to mechanical stops
- Not engaged at level off at FL160
- Airspeed decreased
- About 170 knots flightcrew advanced throttles
- Stall warning activated and upset occurred
- No evidence of autothrottle malfunction





# AA 903 Altitude Plot





# Cockpit


---





# Instrument Diagram

---





# Autothrottle Controls

---

- Engaged via button on glareshield
- Disengage - depress disconnect button on throttle, FMA to amber “MAN THR”, green bars on FCU out
- Other airplanes have warning systems requiring additional flightcrew action
- A300 - passive and persistent indications
- More typical of information display, does not command attention, possible delay between inadvertent disconnect and recognition



# A300 Upset Loss of Displays

---

- Primary flight controls went out momentarily during upset
- Replaced by indication that computers driving the displays were undergoing automatic reset and self-test
- Function designed to detect unreliable data - monitors flight parameters



# A300 Upset Loss of Displays

---

- Reset threshold for roll rate - greater than 40 degrees per second
- Airbus first time reset reported during upset
- Recommendation issued to FAA asking that Airbus modify this software on A300 because of the potential for loss of information during unusual attitude recovery



# What do these accidents tell us?

---

- Role of defaults in adaptive automation
- Effects of high false alarm rates
- Dangers of passive monitoring
- Unanticipated failure modes

*and, that training just won't cover everything*